LEADER IN INDUSTRIAL TOOLS & EQUIPMENT

Technical sheet



WHEEL NUT cover indicator HBL

Marque:

Ref Product: wire:HBL

Ref Mcmining: WHEELNUT------

	DESCRIPTIONS	
WHEEL NUT cover indicator HBL goujons rétroréfléchissant Wheel Nut indicator - Is a loose wheel nut indicator that is used extensively by the Transport industry as an enhancement and Development of fleet safety roadworthiness procedures, daily Walk-round inspection and defect reporting and scheduled maintenance requirements. - allows accurate monitoring for Loose wheel nuts - helps prevent wheel hub damage or the loss of a road wheel should a wheel nut loosen. heat sensitivity : when higher than normal operational temperature are reached, the Wheel Check Indicator is designed to melt indicating an imminent Bearing failure or braking issues. The Wheel Check Indicator is fixed to the wheel nut by gripping the six corners of the hexagon of the wheel nut. When the wheel is being fitted out the Wheel Check Indicator pointers should be aligned and set in a recognizable pattern. Should a wheel nut loosen off, the Wheel Check Indicator has no option but to move with the nut and so break the recognizable pattern that was set, thus indicating the wheel nut has begun to rotate and therefore to loosen. Color: Yellow Material:PP Melting point: 165ºC		
References	**REF MC MINING**	**Fitment**
HBL19	**WHEELNUT19MM-Y**	for 19mm
HBL21	**WHEELNUT21MM-Y**	for 21mm
HBL22	**WHEELNUT22MM-Y**	for 22mm
HBL24	**WHEELNUT24MM-Y**	for 24mm
HBL30	**WHEELNUT30MM-Y**	for 30mm
HBL32	**WHEELNUT32MM-Y**	for 32mm
HBL33	**WHEELNUT33MM-Y**	for 33mm
HBL34	**WHEELNUT34MM-Y**	for 34mm
HBL36	**WHEELNUT36MM-Y**	for 36mm
HBL41	**WHEELNUT41MM-Y**	for 41mm